

		<b>SR3</b>
<b>CONTROL SYSTEM</b>		3)
<b>TRAVEL</b>		
X Axis Travel	mm/inch	762/30
Y Axis Travel	mm/inch	430 / 16.9
Z Axis Travel	mm/inch	460/18.1
Spindle Nose to Table Surface	mm/inch	75~535/3~21
Spindle Center to Column Cover	mm/inch	435/17
<b>TABLE</b>		
Table Size (L x W)	mm/inch	910 x 380 / 36 x 15
T Slot	mm/inch	16 x 80 x 4 slots/ 0.63 x 3.15 x 4 slots
Max. Loading	kgs/lbs	792/ 1746
Standard Loading	kgs/lbs	660/1455
<b>SPINDLE</b>		
Max. Motor Power (Peak)	HP	15
Max. Speed	rpm	9,000
Spindle Taper	ISO 40	BT40
<b>FEED</b>		
Rapid Feed X/Y/Z	M/min rpm	30 / 30 / 24 1181 /1181 /945
Cutting Feed X/Y/Z	M/min rpm	10/10/10 394/394/394
<b>ACCURACY</b>		
Positioning	mm/inch	0.01 /0.00039
Repeatability	mm/inch	±0.003 / ±0.00012
<b>ATC</b>		

<b>ATC</b>	
<b>Tool Storage Arm ATC</b>	<b>20T</b>
<b>Max. Tool Diameter</b>	<b>75/3</b>
<b>Max. Tool Diameter (Without Neighbor Tool)</b>	<b>150 /5.9</b>
<b>Max. Tool Length</b>	<b>250 /9.8</b>
<b>Max. Tool Weight</b>	<b>7/15</b>
<b>Tool to Tool Time (60hz)</b>	<b>2.2</b>
<b>GENERAL</b>	
<b>Tank Capacity</b>	<b>150 / 39.6</b>
<b>Chip Disposal</b>	<b>Drawer</b>
<b>Air Pressure Requirement</b>	<b>0.5/72.5</b>
<b>Power Requirement</b>	<b>20</b>
<b>Floor Space</b>	<b>2100 x 1935 / 83x 76</b>
<b>Weight</b>	<b>3480 /7672</b>